



SIERRA
WIRELESS™

Skylight

Release Notes

Revision:	Build 4601
------------------	-------------------

Copyright © 2016 Sierra Wireless, Inc.

This document contains information which is proprietary and confidential to Sierra Wireless, Inc. Disclosure to persons other than the officers, employees, agents, or subcontractors of the Company or licensee of this document without the prior written permission of Sierra Wireless, Inc. is strictly prohibited.

Document #:		Revision:	Build 4601	Page 2 of 31
-------------	--	-----------	------------	--------------

Table of Contents

1	General	7
1.1	<i>Purpose</i>	7
1.2	<i>Revision Summary</i>	7
2	Revision History	9
2.1	<i>Build 4601</i>	9
2.1.1	Change Details	9
2.1.2	Component List.....	9
2.1.3	Device Drivers	9
2.1.4	Known Issues	9
2.2	<i>Build 4579</i>	9
2.2.1	Change Details	9
2.2.2	Component List.....	9
2.2.3	Device Drivers	9
2.2.4	Known Issues	9
2.3	<i>Build 4568</i>	10
2.3.1	Change Details	10
2.3.2	Component List.....	10
2.3.3	Device Drivers	10
2.3.4	Known Issues	10
2.4	<i>Build 4552</i>	10
2.4.1	Change Details	10
2.4.2	Component List.....	10
2.4.3	Device Drivers	10
2.4.4	Known Issues	11
2.5	<i>Build 4538</i>	11
2.5.1	Change Details	11
2.5.2	Component List.....	11
2.5.3	Device Drivers	11
2.5.4	Known Issues	11
2.6	<i>Build 4527</i>	11
2.6.1	Change Details	11
2.6.2	Component List.....	11
2.6.3	Device Drivers	12
2.6.4	Known Issues	12
2.7	<i>Build 4524</i>	12
2.7.1	Change Details	12
2.7.2	Component List.....	12
2.7.3	Device Drivers	12
2.7.4	Known Issues	12

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 3 of 31
-------------	--	-----------	------------	--------------

2.8	<i>Build 4515</i>	12
2.8.1	Change Details	12
2.8.2	Component List	12
2.8.3	Device Drivers	13
2.8.4	Known Issues	13
2.9	<i>Build 4507</i>	13
2.9.1	Change Details	13
2.9.2	Component List	13
2.9.3	Device Drivers	13
2.9.4	Known Issues	13
2.10	<i>Build 4497</i>	13
2.10.1	Change Details	13
2.10.2	Component List	14
2.10.3	Device Drivers	14
2.10.4	Known Issues	14
2.11	<i>Build 4477</i>	14
2.11.1	Change Details	14
2.11.2	Component List	14
2.11.3	Device Drivers	14
2.11.4	Known Issues	15
2.12	<i>Build 4442</i>	15
2.12.1	Change Details	15
2.12.2	Component List	15
2.12.3	Device Drivers	15
2.12.4	Known Issues	15
2.13	<i>Build 4432</i>	15
2.13.1	Change Details	15
2.13.2	Component List	16
2.13.3	Device Drivers	16
2.13.4	Known Issues	16
2.14	<i>Build 4429</i>	16
2.14.1	Change Details	16
2.14.2	Component List	16
2.14.3	Device Drivers	16
2.14.4	Known Issues	16
2.15	<i>Build 4413</i>	17
2.15.1	Change Details	17
2.15.2	Component List	17
2.15.3	Device Drivers	17
2.15.4	Known Issues	17
2.16	<i>Build 4405</i>	17
2.16.1	Change Details	17
2.16.2	Component List	17
2.16.3	Device Drivers	17
2.17	<i>Build 4393</i>	18

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 4 of 31
-------------	--	-----------	------------	--------------

2.17.1	Change Details	18
2.17.2	Component List.....	18
2.17.3	Device Drivers	18
2.17.4	Known Issues	18
2.18	<i>Build 4378</i>	18
2.18.1	Change Details	18
2.18.2	Component List.....	18
2.18.3	Device Drivers	19
2.18.4	Known Issues	19
2.19	<i>Build 4375</i>	19
2.19.1	Change Details	19
2.19.2	Component List.....	19
2.19.3	Device Drivers	19
2.19.4	Known Issues	19
2.20	<i>Build 4342</i>	19
2.20.1	Change Details	19
2.20.2	Component List.....	20
2.20.3	Device Drivers	20
2.20.4	Known Issues	20
2.21	<i>Build 4328</i>	20
2.21.1	Change Details	20
2.21.2	Component List.....	20
2.21.3	Device Drivers	20
2.21.4	Known Issues	21
2.22	<i>Build 4305</i>	21
2.22.1	Change Details	21
2.22.2	Component List.....	21
2.22.3	Device Drivers	21
2.22.4	Known Issues	21
2.23	<i>Build 4294</i>	21
2.23.1	Change Details	21
2.23.2	Component List.....	22
2.23.3	Device Drivers	22
2.23.4	Known Issues	22
2.24	<i>Build 4290</i>	22
2.24.1	Change Details	22
2.24.2	Component List.....	22
2.24.3	Device Drivers	22
2.24.4	Known Issues	22
2.25	<i>Build 4286</i>	23
2.25.1	Change Details	23
2.25.2	Component List.....	23
2.25.3	Device Drivers	23
2.26	<i>Build 4273</i>	23
2.26.1	Change Details	23

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 5 of 31
-------------	--	-----------	------------	--------------

2.26.2	Component List.....	23
2.26.3	Device Drivers	23
2.27	<i>Build 4260</i>	24
2.27.1	Change Details	24
2.27.2	Component List.....	24
2.27.3	Device Drivers	24
2.27.4	Known Issues	24
2.28	<i>Build 4255</i>	24
2.28.1	Change Details	24
2.28.2	Component List.....	24
2.28.3	Device Drivers	24
2.28.4	Known Issues	24
2.29	<i>Build 4248</i>	24
2.29.1	Change Details	24
2.29.2	Component List.....	25
2.29.3	Device Drivers	25
2.29.4	Known Issues	25
2.30	<i>Build 4243</i>	25
2.30.1	Change Details	25
2.30.2	Component List.....	25
2.30.3	Device Drivers	25
2.30.4	Known Issues	25
2.31	<i>Build 4230</i>	25
2.31.1	Change Details	25
2.31.2	Component List.....	26
2.31.3	Device Drivers	26
2.31.4	Known Issues	26
2.32	<i>Build 4209</i>	26
2.32.1	Change Details	26
2.32.2	Component List.....	26
2.32.3	Known Issues	26
2.33	<i>Build 4207</i>	27
2.33.1	Change Details	27
2.33.2	Component List.....	27
2.33.3	Known Issues	27
2.34	<i>Build 4202</i>	27
2.34.1	Change Details	27
2.34.2	Component List.....	27
2.34.3	Known Issues	27
2.35	<i>Build 4193</i>	27
2.35.1	Change Details	27
2.35.2	Component List.....	28
2.35.3	Known Issues	28
2.36	<i>Build 4173</i>	28
2.36.1	Change Details	28

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 6 of 31
-------------	--	-----------	------------	--------------

- 2.36.2 Component List..... 28
- 2.36.3 Known Issues 29
- 2.37 *Build 4166*..... 29
 - 2.37.1 Change Details 29
 - 2.37.2 Component List..... 29
 - 2.37.3 Known Issues 29
- 2.38 *Build 4140*..... 29
 - 2.38.1 Change Details 29
 - 2.38.2 Component List..... 29
 - 2.38.3 Known Issues 29
- 2.39 *Build 4130*..... 30
 - 2.39.1 Change Details 30
 - 2.39.2 Component List..... 30
 - 2.39.3 Known Issues 30
- 2.40 *Build 4106*..... 30
 - 2.40.1 Change Details 30
 - 2.40.2 Component List..... 30
 - 2.40.3 Known Issues 30
- 2.41 *Build 4094*..... 30
 - 2.41.1 Change Details 30
 - 2.41.2 Component List..... 31
 - 2.41.3 Known Issues 31
- 2.42 *Build 4072*..... 31
 - 2.42.1 Change Details 31
 - 2.42.2 Component List..... 31
 - 2.42.3 Known Issues 31

Document #:		Revision:	Build 4601	Page 7 of 31
-------------	--	-----------	------------	--------------

1 General

1.1 Purpose

This document is intended to capture technical changes to the Skylight software release package.

These release notes are NOT intended for the end user.

1.2 Revision Summary

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 8 of 31
-------------	--	-----------	------------	--------------

Date	Build
October 21, 2016	Build 4601
September 23, 2016	Build 4579
August 26, 2016	Build 4568
August 3, 2016	Build 4552
July 12, 2016	Build 4538
June 24, 2016	Build 4527
June 3, 2016	Build 4524
May 20, 2016	Build 4515
April 29, 2016	Build 4507
April 20, 2016	Build 4497
March 18, 2016	Build 4477
Feb 15, 2016	Build 4442
Jan 18, 2016	Build 4432
Dec 18, 2015	Build 4429
Dec 3, 2015	Build 4413
Nov 6, 2015	Build 4405
Oct 23, 2015	Build 4393
Sept 25, 2015	Build 4378
Sep 15, 2015	Build 4375
Sep 11, 2015	Build 4342
Aug 14, 2015	Build 4328
June 5, 2015	Build 4305
May 22, 2015	Build 4294
May 1, 2015	Build 4290
April 23, 2015	Build 4286
March 27, 2015	Build 4273
Feb 27, 2015	Build 4260
Feb 17, 2015	Build 4255
Feb 4, 2015	Build 4248
January 22, 2015	Build 4243
December 17, 2014	Build 4230
November 14, 2014	Build 4209
October 3, 2014	Build 4207
September 26, 2014	Build 4202
September 5, 2014	Build 4193
August 22, 2014	Build 4173
July 23, 2014	Build 4166
June 27, 2014	Build 4140
June 6, 2014	Build 4130
May 9, 2014	Build 4106
April 4, 2014	Build 4094
February 28, 2014	Build 4072

Document #:		Revision:	Build 4601	Page 9 of 31
-------------	--	-----------	------------	--------------

2 Revision History

2.1 Build 4601

2.1.1 Change Details

- HSWSKYL-205 [Skylight] Uninstall.exe remains after re-installing Skylight in a custom folder
- HSWSKYL-206 [Skylight] SIM Security Settings show incorrect and greyed out values
- HSWSKYL-207 Skylight crashes when receiving certain SMS message

2.1.2 Component List

Component	Revision
Skylight.exe	13.0.1610.0
QmiPlugin.dll	13.0.1610.0
GobiApi.dll	4.2.1610.1

2.1.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with 9x15 driver build 4600.

2.1.4 Known Issues

- None

2.2 Build 4579

2.2.1 Change Details

- HSWSKYL-190 [Getac] Fixed main view signal bar display issue in Windows 7
- HSWSKYL-195 [Internal] Fixed profile dropdown box updating issue

2.2.2 Component List

Component	Revision
Skylight.exe	13.0.1609.0
QmiPlugin.dll	13.0.1609.0
GobiApi.dll	4.2.1608.1

2.2.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with 9x30 driver build 4566.

2.2.4 Known Issues

- [HSWSKYL-199] Build 4568 Silent install prompts missing mfc140u.dll

Document #:		Revision:	Build 4601	Page 10 of 31
-------------	--	-----------	------------	---------------

2.3 Build 4568

2.3.1 Change Details

- HSWSKYL-167 [Skylight] Build request for Toshiba
- HSWSKYL-180 [Skylight] Wrong PIN prompted before attempting to unlock PIN a second time
- HSWSKYL-70 [Skylight] [SMS Express] Recipient Number is Shown Twice in Sent Items Folder
- HSWSKYL-172 [Skylight] Phone Book is always launched full screen
- HSWSKYL-174 [AR755x][ntt docomo] Unable to send SMS containing special characters

2.3.2 Component List

Component	Revision
Skylight.exe	13.0.1608.0
QmiPlugin.dll	13.0.1608.0
GobiApi.dll	4.2.1608.1

2.3.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with 9x30 driver build 4566.

2.3.4 Known Issues

- HSWSKYL-69 [Skylight] [SMS Express] 10 Segment Concatenated SMS Disappears from Sent Items Folder after Skylight Restart

2.4 Build 4552

2.4.1 Change Details

- HSWSKYL-152 [Fujitsu] Minimized Skylight UI issues when changing tablet orientation
- HSWSKYL-155 [Fujitsu] Skylight build request
- HSWSKYL-162 [Fujitsu] GPS Monitor Change Request
- HSWSKYL-151 [Fujitsu] Skylight shows -1 retries remaining when locking sim
- HSWSKYL-157 Unable to change name of default profile
- HSWSKYL-158 Last deleted profile recreated after restarting Skylight
- HSWSKYL-136 Remaining attempts for disabling SIM Security shows incorrect value

2.4.2 Component List

Component	Revision
Skylight.exe	13.0.1607.0
QmiPlugin.dll	13.0.1607.0
GobiApi.dll	4.2.1607.0

2.4.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with 9x30 driver build 4539.

Document #:		Revision:	Build 4601	Page 11 of 31
-------------	--	-----------	------------	---------------

2.4.4 Known Issues

- HSWSKYL-165 Skylight Connection fails after auto connect is set

2.5 Build 4538

2.5.1 Change Details

- HSWSKYL-129 Fixed data connection problems following S3 resume.
- HSWSKYL-123 Fixed blank APN profile issues.
- HSWSKYL-137 Fixed occasional empty default profile list.
- HSWSKYL-132 Fixed issue when deleting last profile.
- HSWSKYL-141 SIM ICCID is now hidden for all Japanese operators.
- HSWSKYL-138 Updated icon in Control Panel -> Programs and Features.
- HSWSKYL-136 Fixed remaining attempts value following SIM security disable.
- HSWSKYL-140 Implemented installer command option for manual image switching.
- HSWSKYL-133 Added optional Skylight desktop shortcut – command line parameter.

2.5.2 Component List

Component	Revision
Skylight.exe	13.0.1606.2
QmiPlugin.dll	13.0.1606.2
GobiApi.dll	4.2.1606.0

2.5.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4516 (9x15) and 4521 (9x30).

2.5.4 Known Issues

- HSWCARP-27 Remaining retries field not updated correctly when locking SIM.

2.6 Build 4527

2.6.1 Change Details

- HSWSKYL-85 [EM7455][Skylight] Remove Skylight Activation Wizard on Sprint network
- HSWSKYL-92 [Getac] Add “DefaultView” and “SMSNotif” Skylight installation command line options
- HSWSKYL-93 [Fujitsu] Skylight failed to connect to a PRIVATE APN
- HSWSKYL-121 [Panasonic] Remove Radio Power On/Off menu from Skylight
- HSWGPSM-5 Added support to RecurrenceType and OperationMode LOC service settings

2.6.2 Component List

Component	Revision
Skylight.exe	13.0.1606.1
QmiPlugin.dll	13.0.1606.0
GobiApi.dll	4.2.1605.1

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 12 of 31
-------------	--	-----------	------------	---------------

2.6.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4516 (9x15) and 4521 (9x30).

2.6.4 Known Issues

- HSWSKYL-98 [Skylight] GPS Monitor Crashes after Hibernating and Resuming the laptop
- HSWSKYL-123 [EM7455][Skylight] Profile's APN disappears after creation and setting it to default

2.7 Build 4524

2.7.1 Change Details

- HSWGPM-4 Remove read-only GPS Monitor settings
- HSWSKYL-64 Change Skylight Firmware Update message in Japanese localization
- HSWSKYL-67 Skylight fails to respond during image switch
- HSWSKYL-74 Skylight Profile name has last letter missing
- HSWSKYL-76 Prevent connection until profiles are read from device
- HSWSKYL-83 Support all GPS devices in GPS Monitor

2.7.2 Component List

Component	Revision
Skylight.exe	13.0.1606.0
QmiPlugin.dll	13.0.1605.0
GobiApi.dll	4.2.1605.1

2.7.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4516 (9x15) and 4521 (9x30).

2.7.4 Known Issues

2.8 Build 4515

2.8.1 Change Details

- HSWSKYL-10 Require a Skylight Build that can send 10 concatenated SMS messages.
- HSWSKYL-46 Device has an option to Enable/Disable PIN 1
- HSWSKYL-54 [Skylight] Logic update to use new APIs for signal strength threshold
- HSWSKYL-59 [Skylight] Default profile changes every time when Skylight is closed and reopened.
- HSWSKYL-61 Need to be able to disable Network Initiated Alerts.
- HSWSKYL-66 Panasonic Skylight release needed to include all recent fixes

2.8.2 Component List

Component	Revision
Skylight.exe	13.0.1605.0

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 13 of 31
-------------	--	-----------	------------	---------------

QmiPlugin.dll	13.0.1605.0
GobiApi.dll	4.2.1605.0

2.8.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4516 (9x15) and 4509 (9x30).

2.8.4 Known Issues

- HSWSKYL-67 [9x30] Skylight UI stuck (~30s) in firmware update state after initiating a switch to firmware image stored on the modem

2.9 Build 4507

2.9.1 Change Details

- HSWSKYL-19: (Win10) Fixed updating APN after removing it.
- HSWSKYL-47: Fixed default profile in Main UI change when invoking "User Options - >Profiles".
- HSWSKYL-48: Fixed disabling auto-connect default profile feature.
- HSWSKYL-53 Fixed updating username and password on existing profiles.

2.9.2 Component List

Component	Revision
Skylight.exe	13.0.1604.0
QmiPlugin.dll	13.0.1604.1
GobiApi.dll	4.2.1604.2

2.9.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4431 (9x15) and 443 (9x30).

2.9.4 Known Issues

- None

2.10 Build 4497

2.10.1 Change Details

- HSWSKYL-23 Fixed connection profile updates when profile was created by Windows
- HSWSKYL-19 Fixed updating profile APN after deleting
- HSWSKYL-31 [Sprint] Invalid PUK unlock is only allowed one time then correct PUK doesn't unlock
- HSWSKYL-32 Fixed unrecognized characters in the firmware details (Verizon image.)
- HSWSKYL-34 Fixed "Not Activated" status displayed following firmware update.
- HSWOEMP-57 Fixed data session startup following SIM hot swap with invalid SIM.
- HSWSKYL-41 [GPS Monitor] Fixed mapping URL issue.
- HSWSKYL-35 [Toshiba-Lite] Fixed 'Failed to write profile' error
- HSWSKYL-36 [Toshiba-Lite] Fixed occasional crash when reading device profile

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 14 of 31
-------------	--	-----------	------------	---------------

- HSWSKYL-12 [Toshiba-Lite][Intel] Added support for profile management on Win7
- SBM20441 [SMS Express] Stored sent Items timestamp on the host.

2.10.2 Component List

Component	Revision
Skylight.exe	13.0.1604.0
QmiPlugin.dll	13.0.1604.0
GobiApi.dll	4.2.1604.1

2.10.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4431 (9x15) and 443 (9x30).

2.10.4 Known Issues

- None

2.11 Build 4477

2.11.1 Change Details

- CUS87403 [MC7430][Telstra][IOTAS] Addressed Telstra 3G/4G Signal Bar mapping requirements.
- ANO79026 [EM7455] Fixed incorrect display of "User Options->SIM Settings->SIM Security->Enabled".
- SBM20379 Fixed disconnection sound being played twice.
- SBM20431 [Toshiba Light] Fixed profile name changing issues after profile creation.
- SBM20436 [Toshiba Light] Fixed Profile deletion issue after Profile name change.
- SBM20441 [SMS Express] Fixed "Sent Items" timestamp clearing on Skylight restart.
- SBM20456 [SMS Express] Fixed toolbars cutoff UI issue on Win10 with scaling > 100%.
- HSWSKYL-19 [Toshiba Light] Fixed profile APN changing issues after profile creation.
- HSWSKYL-15 [Phonebook] Fixed toolbars cutoff issue on Win10 with scaling > 100%.
- HSWSKYL-14 Added support for large Cell Broadcast text message (Class 0 SMS, CMAS, and ETWS).
- HSWSKYL-18 Added support for extended carrier image information in About dialog display.
- HSWSKYL-20 Fixed automatic SIM matched profile parameters in profile page.

2.11.2 Component List

Component	Revision
Skylight.exe	13.0.1603.0
QmiPlugin.dll	13.0.1603.0
GobiApi.dll	4.2.1603.1

2.11.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4431 (9x15) and 443 (9x30).

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 15 of 31
-------------	--	-----------	------------	---------------

2.11.4 Known Issues

- None

2.12 Build 4442

2.12.1 Change Details

- ANO 78427 [WIN10] Fixed default profile auto-connection issue.
- SBM 20050 Added display of "*****" for profile's password when profile username is present.
- [JIRA] (HSWSKYL-8) Fixed Speed-graph displaying by Default.
- SBM 19716 Added support for hardware switching of radio state.
- SBM 20304 Changed default Sprint APN from cinet.spcs to r.ispsn.
- CUS87403 [Telstra] Addressed Telstra's required signal strength bar map.
- SBM20313 [Win10] Fixed Non-SIM associated profile's APN is overwritten.
- SBM20308 [Win10] Fixed default profile prompt for password storage.
- SBM20373 [Win10] Fixed selection and switching of default profile.
- SBM20374 [Win10] Fixed saving of default profile username and password.
- SBM19895 [Win10] Added support for none-default profiles on the host.
- SBM20264 [Win10][EM7455] Fixed default profile auto-connect option.
- SBM20113 Display Skylight's icon in system tray only when minimized.
- SBM19875 Fixed greyed out connect button after resuming from hibernate.
- SBM19731 Fixed Auto-connect reverting back to "Never" after modem reset.
- SBM20003 Fixed re-entering profile's password when invoking a URL.
- SBM20302 Fixed occasional Skylight crash when disabling/enabling mobile broadband.
- SBM 19772 Fixed "No SIM inserted" display when removal/insertion of SIM and selecting options menu dropdown during data session.

2.12.2 Component List

Component	Revision
Skylight.exe	13.0.1601.1
QmiPlugin.dll	13.0.1601.1
GobiApi.dll	4.2.1601.2

2.12.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4414 (9x15) and 4452 (9x30).

2.12.4 Known Issues

- SBM 20379 When disconnecting from data connection, disconnecting sound played twice.

2.13 Build 4432

2.13.1 Change Details

- CUS83371 [Skylight][Telefonica] SMS Class 0 support

Copyright © 2016 Sierra Wireless, Inc.

The contents of this page are subject to the confidentiality information on page one.

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 16 of 31
-------------	--	-----------	------------	---------------

- SBM20114 [Skylight] SMS timestamp for Rec message is incorrect.
- SBM20115 [Skylight] SIMPIN change shows failed operation
- SBM20113 [Skylight] Skylight shown in Taskbar and also in System Tray
- SBM20152 [Skylight] Stability improvement

2.13.2 Component List

Component	Revision
Skylight.exe	13.0.1601.0
QmiPlugin.dll	13.0.1601.0
GobiApi.dll	4.2.1601.0

2.13.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4414 (9x15) and 4427 (9x30).

2.13.4 Known Issues

- SBM19731 [Win10][Rogers] Auto-connect reverts back to Never after modem reset.
- SBM20001 [Win10] Auto-connect reverts back to Never.
- Win10 profile management issues

2.14 Build 4429

2.14.1 Change Details

- SBM20025 [EM7355] [Dell] Skylight stop working
- SBM20118 [Skylight] FW manual/auto settings change request
- SBM19999 [EM7305] 1102152 Skylight CANNOT CAMP to Live Network after Win7 cold-boot
- SBM20126 [Skylight] "operation failure" when change pin
- SBM20134 [Skylight] Profile UI Control flickering
- SBM20076 [Skylight] Wrong Component ID
- SBM20073 [Skylight] Crash when trying to connect with Application Verifier

2.14.2 Component List

Component	Revision
Skylight.exe	13.0.1512.1
QmiPlugin.dll	13.0.1512.0
GobiApi.dll	4.2.1511.3

2.14.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4414 (9x15) and 4427 (9x30).

2.14.4 Known Issues

- SBM19731 [Win10][Rogers] Auto-connect reverts back to Never after modem reset.
- SBM20001 [Win10] Auto-connect reverts back to Never.
- Win10 profile management issues

Document #:		Revision:	Build 4601	Page 17 of 31
-------------	--	-----------	------------	---------------

2.15 Build 4413

2.15.1 Change Details

- SBM19999 [EM7305][Win7] Skylight can't camp on live network after cold boot-up.
- SBM19877 [EM7455] Skylight crashes when invoking "User Options->Firmware" page.
- SBM19995 [EM7455][Win7] Fixed GPS Monitor crash after invoking setting page.
- SBM19967 [EM7355] SwiService stops after switching firmware to Sprint.
- SBM19805 Skylight displays "Updating firmware..." after successful firmware updates.
- SBM19850 Fixed occasional disabling of the "Connect" button

2.15.2 Component List

Component	Revision
Skylight.exe	13.0.1511.1
QmiPlugin.dll	13.0.1511.1
GobiApi.dll	4.2.1511.1

2.15.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4414 (9x15) and 4418 (9x30).

2.15.4 Known Issues

- SBM19731 [Win10][Rogers] Auto-connect reverts back to Never after modem reset.
- SBM20001 [Win10] Auto-connect reverts back to Never.
- Win10 profile management issues

2.16 Build 4405

2.16.1 Change Details

- SBM19743 Improved Skylight responsiveness when resuming from hibernate.
- SBM19692 Implemented display of DPR control values in Skylight About dialog (in advanced mode).
- ANO79756 Fixed turning radio on after entering Mobile Broadband radio off State when modem is connected.
- SBM19780 [GPS Monitor] Fixed display of user location using Google Maps.

2.16.2 Component List

Component	Revision
Skylight.exe	13.0.1511.0
QmiPlugin.dll	13.0.1511.0
GobiApi.dll	4.2.1511.0

2.16.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4382_Eng2 (9x15) and 4398_ENG9 (9x30).

Document #:		Revision:	Build 4601	Page 18 of 31
-------------	--	-----------	------------	---------------

2.17 Build 4393

2.17.1 Change Details

- SBM18198 Fixed firmware version display issue in About->Device->Firmware page
- SBM19723 Fixed SMS Express displaying text issue.
- SBM19672 Fixed MEP unlock using Skylight.
- SBM19644 Fixed Skylight minimized default issue.
- SBM18991 [EM7445] Fixed SIM detection problem.
- SBM19727/SBM19747/SBM19748/SBM19772 Addressed [several](#) SIM eject/insert issues.
- SBM19215 [GPS Monitor] Added option to delete GPS assist data.
- SBM19629 [GPS Monitor] Fixed GPS auto-start feature.
- SBM19658 [GPS Monitor] Added support for Privacy Mode.
- SBM19755 [DELL] Fixed event viewer Application Error 1000 when launching Skylight.

2.17.2 Component List

Component	Revision
Skylight.exe	13.0.1510.0
QmiPlugin.dll	13.0.1510.0
GobiApi.dll	4.2.1509.0

2.17.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4368_ENG2 (9x15) and 4376_ENG3 (9x30).

2.17.4 Known Issues

- SBM19780 [GPS Monitor] Google Maps does not display the correct location, Bing does
- SBM19731 [Win10][Rogers] Auto-connect reverts back to Never after modem reset.
- SBM19743 [Win10] Skylight not responsive after resuming from hibernate for 1-2 minute(s).

2.18 Build 4378

2.18.1 Change Details

- SBM18172 [GPS Monitor] Start Tracking button is unresponsive after re-installing driver
- SBM18211 [Skylight] Auto-connect causes skylight to stop displaying data information on GUI after restart and shutdown
- SBM18991 [Skylight] Skylight could not detect SIM when it is removed and re-inserted
- SBM19460 [GPS Monitor] Display in-view and used satellite PRN value
- SBM19535 [Skylight] Customer private APN username and password were logged in clear text
- SBM19538 [Skylight] Show USB type in Skylight

2.18.2 Component List

Component	Revision
Skylight.exe	13.0.1509.1

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 19 of 31
-------------	--	-----------	------------	---------------

QmiPlugin.dll	13.0.1509.1
GobiApi.dll	4.2.1509.0

2.18.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4368_ENG2 (9x15) and 4376_ENG3 (9x30).

2.18.4 Known Issues

- SBM19573 [Skylight] SIM Setting is missing in User Option with Panasonic PRI
- SBM19612 [Skylight] [EM7455] SMS Express on Win10 32-bit receives same Duplicated SMS Message Twice
- SBM19629 [Skylight][GPS Monitor] Auto starts GPS session on 32-bit Windows

2.19 Build 4375

2.19.1 Change Details

- SBM19277 [PTCRB] Skylight adds Extra 0 to 2 Digit MNCs for CSG Scan

2.19.2 Component List

Component	Revision
Skylight.exe	13.0.1509.0
QmiPlugin.dll	13.0.1509.1
GobiApi.dll	4.2.1508.3

2.19.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4323 (9x15) and 4337 (9x30).

2.19.4 Known Issues

- None

2.20 Build 4342

2.20.1 Change Details

- CUS83541 [EM7455][AT&T] Skylight now immediately is in synch when service provider changes
- CUS83006 [EM7455][Orange] Fixed double display of SMS in the SMS Express inbox
- CUS82110 [Dell] [EM7455] [Driver Installer] [Skylight Installer] Improved grammar for other languages
- BM19277 [PTCRB] Fixed SIM's MNC number of digits (2 or 3) display
- SBM19376 [Skylight] Fixed "Device in Safety Mode" display after turning off Mobile Broadband
- SBM18211 [Skylight] [Intel] [EM7345] Fixed auto-connect that causes skylight to stop displaying data information on GUI after restart and shutdown
- SBM19388 [Skylight][Sprint] Fixed "Not Activated" Skylight state following updating the default profile

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 20 of 31
-------------	--	-----------	------------	---------------

- SBM19463 [Skylight][Sprint] Display MSID and PRL in Help->About->Subscriber page
- SBM18991 [Skylight] [Lenovo][EM7445] Fixed SIM detection issue
- SBM19282 [Skylight] Fixed GPS Monitor not being re-launched after closing Skylight with GPS Monitor open
- SBM19282 [GPS Monitor] Fixed GPS Monitor termination issue when closing Skylight
- SBM19312 [GPS Monitor] Fixed GPS Monitor stopping during driver re-installation
- SBM19215 [GPS Monitor] Added option to delete GPS assist data

2.20.2 Component List

Component	Revision
Skylight.exe	13.0.1508.0
QmiPlugin.dll	13.0.1509.0
GobiApi.dll	4.2.1508.3

2.20.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4323 (9x15) and 4337 (9x30).

2.20.4 Known Issues

- None

2.21 Build 4328

2.21.1 Change Details

- CUS81692 [Skylight][EM7455] Addressed SIM Security (PIN attempts counter)
- CUS81693 [Skylight][EM7455] Addressed SIM Security (PUK attempts counter)
- SBM18727 [Skylight] Customer's DNS settings in Skylight are overwritten after data connection
- SBM19140 [Skylight] [GPS Monitor] Remove Yahoo Map from search URL list
- SBM19183 [Skylight][EM7455] Remove Windows Mobile Broadband user option
- SBM19123 [GPS Monitor] Simultaneous support both Gobi/QMI API and Location API
- SBM18002 [GPS Monitor] GPS continues tracking after being cancelled
- SBM19027 [Skylight] Support profiles with user names longer than 32 characters
- ANO80721 [Skylight] Firmware Section in User Options constantly stays in "Processing..." state

2.21.2 Component List

Component	Revision
Skylight.exe	13.0.1507.1
QmiPlugin.dll	13.0.1507.1
GobiApi.dll	4.2.1507.1

2.21.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4323 (9x15) and 4337 (9x30).

Document #:		Revision:	Build 4601	Page 21 of 31
-------------	--	-----------	------------	---------------

2.21.4 Known Issues

- SBM19282 [GPS Monitor] GPS Monitor may not terminate when closing Skylight
- SBM19312 [GPS Monitor] GPS Monitor stops working during driver re-installation

2.22 Build 4305

2.22.1 Change Details

- ANO79777 [EM7455][Skylight] SMS Express freezes when trying to select any Inbox message
- ANO80725 [EM7455][Skylight] SIM with Expired PUK is not detected
- SBM18506 [EM7345][Skylight] Profile settings are not accessible without a SIM
- SBM18703 [Skylight] Concatenate "default" word to default profile in "User Options->Profiles"; and display profile ID in advanced mode
- SBM18727 [EM7355] Customer's DNS settings in Skylight are overwritten after connection
- SBM18876 [GPS Monitor] Cancelling GPS tracking on Win8 and above turns GPS radio off

2.22.2 Component List

Component	Revision
Skylight.exe	13.0.1506.0
QmiPlugin.dll	13.0.1506.1
GobiApi.dll	4.2.1505.1

2.22.3 Device Drivers

- Device drivers are not included and must be installed separately. Tested with driver build 4302.

2.22.4 Known Issues

- ANO80721 [Skylight] Firmware Section in User Options constantly says "Processing..."

2.23 Build 4294

2.23.1 Change Details

- SBM18529 [Skylight] Cannot create new profiles once all profiles are deleted
- SBM18716 [Skylight] After changing Network Selection Mode from Manual Rogers (4G) to Automatic Skylight crashes
- SBM18813 EM7340 Module not detected in Skylight
- ANO79671 [Skylight] 20 Second delay for Skylight to show the network operator vs Van UI
- ANO79677 [Skylight] Crash is observed when selecting items on Skylight - Menu - About in Advanced Mode
- ANO79679: [Skylight] SIM Security incorrectly shows Enabled as "Yes" and Remaining unlock attempts as "0"
- ANO79681 [Skylight] Options - Firmware - Network Operator incorrectly shows as AT&T
- ANO79682 [Skylight] Received SMS's are blank

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 22 of 31
-------------	--	-----------	------------	---------------

- ANO79734 [Skylight] Skylight Crashes When Changing Network Selection Mode from Manual to Automatic
- ANO79776 [Skylight] GPS button on Skylight's main pane is missing
- ANO79777 [Skylight] SMS Express freezes when trying to select any Inbox message
- ANO80725 [Skylight] SIM with Expired PUK is not detected

2.23.2 Component List

Component	Revision
Skylight.exe	13.0.1505.0
QmiPlugin.dll	13.0.1505.0
GobiApi.dll	4.2.1505.0

2.23.3 Device Drivers

- Device drivers are not included and must be installed separately

2.23.4 Known Issues

-

2.24 Build 4290

2.24.1 Change Details

- SBM 18140 [Skylight] SMS Broadcast Type Messages not Shown in Skylight After Auto-launch
- SBM 18632 [GPS Monitor] Runtime detection of QMI location service
- SBM 18568 [Skylight] GPS Monitor QMI_LOC Support
- ANO 79368 [Skylight] [GPS Monitor] [EM7455] No Satellites are displayed after pausing and starting a GPS Session
- SBM 18644 [Skylight][GPS Monitor] Could not find/initialize supported device
- SBM 18488 [SwiDiag][Skylight] SwiDiag not Translated to expected language
- SBM 18649 [Skylight] [Intel] [EM7345] Radio Access Technology appears and cannot be changed in Network Selection Option

2.24.2 Component List

Component	Revision
Skylight.exe	13.0.1504.0
QmiPlugin.dll	13.0.1504.0
GobiApi.dll	4.2.1503.0

2.24.3 Device Drivers

- Device drivers are not included and must be installed separately

2.24.4 Known Issues

- SBM 18544 [AT&T] SMS Requirements
- SBM 18567 Getac T8 tablet, APN not updating in Menu, Connections, Profiles
- SBM 18529 [Skylight] Cannot create new profiles once all profiles are deleted
- SBM 18663 [Skylight] Skylight shows "SIM not inserted" for 2 minutes after Firmware Switches

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 23 of 31
-------------	--	-----------	------------	---------------

- SBM 18646 [Skylight] [Intel] [EM7345] Skylight stops responding after pressing connect and disconnect multiple times
- SBM 18506 [Skylight] [Intel] [EM7345] Cannot access profile settings without a SIM
- SBM 18211 [Skylight] [Intel] [EM7345] Auto-connect causes skylight to stop displaying data information on GUI after restart and shutdown
- SBM 18200 [Skylight] [Intel] [EM7345] Manual Network Selection does not work
- SBM 18280 [Skylight] [Intel] [EM7345] GPS stops updating

2.25 Build 4286

2.25.1 Change Details

- SBM 18568 [Skylight] GPS Monitor QMI_LOC Support
- SBM 18457 [Skylight] Disable WebUpdater
- SBM 18303 [Skylight] Dell Skylight B4209 cannot recognize the EM7455 1102424. need Skylight latest SKU for Dell/EM7455
- SBM 18089 [Dell][Installer and Skylight] MUP 2.4.3 release support

2.25.2 Component List

Component	Revision
Skylight.exe	13.0.1503.0
QmiPlugin.dll	13.0.1503.0
GobiApi.dll	4.2.1503.0

2.25.3 Device Drivers

- Device drivers are not included and must be installed separately

2.26 Build 4273

2.26.1 Change Details

- SBM 17184 Fixed occasional/untimely refresh of "User Options->Profiles" while user updating profile.
- SBM 18103 [Verizon] Fixed manual network selection of "LTE Only".
- SBM 17969 Fixed disconnect failure after resuming from sleep when auto-connection is enabled

2.26.2 Component List

Component	Revision
Skylight.exe	13.0.1503.0
QmiPlugin.dll	13.0.1503.0
GobiApi.dll	4.2.1502.1

2.26.3 Device Drivers

- Device drivers are not included and must be installed separately

Document #:		Revision:	Build 4601	Page 24 of 31
-------------	--	-----------	------------	---------------

2.27 Build 4260

2.27.1 Change Details

- SBM 17456 [GPS Monitor] Use Location APIs instead of Gobi API
- SBM 17130 Add support for CMAS and ETWS SMS
- SBM 17455 Add support for Skylight auto-launch when a "Sierra Wireless EM7345 4G LTE" is detected
- SBM 17523 Use ICCID instead of MCC/MNC (ITU Standard)

2.27.2 Component List

Component	Revision
Skylight.exe	13.0.1502.1
QmiPlugin.dll	12.0.1502.0
GobiApi.dll	4.2.1502.0

2.27.3 Device Drivers

- Device drivers are not included and must be installed separately

2.27.4 Known Issues

- SBM 17969 [Skylight] After resuming from sleep, auto-connection is established briefly before disconnecting

2.28 Build 4255

2.28.1 Change Details

- SBM 17764 [Panasonic Skylight] Build request to have auto-create and auto-select set to never

2.28.2 Component List

Component	Revision
Skylight.exe	13.0.1501.1
QmiPlugin.dll	12.0.1501.0
GobiApi.dll	4.2.1412.2

2.28.3 Device Drivers

- Device drivers are not included and must be installed separately

2.28.4 Known Issues

2.29 Build 4248

2.29.1 Change Details

- SBM 17615 [Panasonic] Profile management feature(s) for enterprise customers
- SBM 17764 [Panasonic] Build request to have auto-create and auto-select set to never

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 25 of 31
-------------	--	-----------	------------	---------------

2.29.2 Component List

Component	Revision
Skylight.exe	13.0.1501.1
QmiPlugin.dll	12.0.1501.0
GobiApi.dll	4.2.1412.2

2.29.3 Device Drivers

- Device drivers are not included and must be installed separately

2.29.4 Known Issues

- SBM 17673 On VZN after at!reset data connection can no longer be made
- SBM 16569 [Skylight] Usage icon shows "Display GPS" randomly

2.30 Build 4243

2.30.1 Change Details

- SBM 17184 Skylight – Fixed profile UI flickering during network registration and deregistration.
- SBM 17480 [Fujitsu] Skylight - Removed "Windows Update - Allow over Wireless WAN connection (3G/4G)" in Win8.x.
- SBM 16427 [Fujitsu] Skylight - Fixed incorrect tooltip text for Speed Graph button when Mobile Broadband is turned off.

2.30.2 Component List

Component	Revision
Skylight.exe	13.0.1501.0
QmiPlugin.dll	12.0.1410.0
GobiApi.dll	4.2.1412.2

2.30.3 Device Drivers

- Device drivers are not included and must be installed separately

2.30.4 Known Issues

- SBM 17348 [Skylight] Event Viewer shows Application Error, Event 1000

2.31 Build 4230

2.31.1 Change Details

- SBM 17263 "AutoLaunch when SMS received" is in Options when SMS is not supported
- SBM 17170 Skylight displays "Not Activated" after switching images from Sprint to Generic
- SBM 16426 Add ATT CSG support in Skylight
- SBM 15956 Skylight does not Disconnect properly on Win7
- SBM 17315 Skylight freezes when turning off mobile broadband
- SBM 17307 Empty settings in User Options -> Messaging->Outgoing Messages

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 26 of 31
-------------	--	-----------	------------	---------------

2.31.2 Component List

Component	Revision
Skylight.exe	13.0.1412.0
QmiPlugin.dll	12.0.1410.0
GobiApi.dll	4.2.1411.1

2.31.3 Device Drivers

- Device drivers are not included and must be installed separately

2.31.4 Known Issues

- SBM 17348 [Skylight] Event Viewer shows Application Error, Event 1000
- SBM 17359 [SwiDiagUtil] After running the SwiDiagUtil the "MobileBroadband" folder is not created

2.32 Build 4209

2.32.1 Change Details

- SBM 16426 Add ATT CSG (Closed subscriber group) support
- SBM 16617 Add support to Windows Updates over MB connections options
- SBM 16588 Skylight sometimes displays 'searching' then "Mobile Broadband is off" when Mobile Broadband is turned off
- SBM 16692 More clear display of build number in Skylight Help->About
- SBM 16761 [GPS Monitor] Map button will bring up Google Maps with We could not find "location"
- SBM 16773 [EM7305] Skylight displays "Searching... Please wait.." when turning on mobile broadband
- SBM 16859 Skylight crashes when clicking Connect button with MC9090
- SBM 16880 [GPS Monitor] Map button brings up Yahoo Maps with the wrong location
- SBM 16881 [GPS Monitor] Map button brings up Bing Maps with the wrong location
- SBM 16897 [GPS Monitor] Change the Altitude units of measurement to lower case m
- SBM 16906 Skylight RF_off not accessible after S3 or S4
- SBM 16938 Skylight crashes when SL9090 module resets

2.32.2 Component List

Component	Revision
Skylight.exe	13.0.1410.1
QmiPlugin.dll	12.0.1410.0
GobiApi.dll	4.2.1410.3

2.32.3 Known Issues

- Device drivers are not included and must be installed separately

Document #:		Revision:	Build 4601	Page 27 of 31
-------------	--	-----------	------------	---------------

2.33 Build 4207

2.33.1 Change Details

- SBM 16585 Sound files path (User Options -> Sounds) opens incorrect folder when selected
- SBM 16572 GPS Button is missing on Skylight after reboot

2.33.2 Component List

Component	Revision
Skylight.exe	13.0.1410.0
QmiPlugin.dll	12.0.1408.0
GobiApi.dll	4.2.1409.0

2.33.3 Known Issues

- Device drivers are not included and must be installed separately
- Windows update over WWAN setting is not available

2.34 Build 4202

2.34.1 Change Details

- SBM 16402 Logging out and Logging in of PC will cause GPS Monitor to be unresponsive
- SBM 16383 Skylight crashes after receiving multiple SMS
- SBM 16162 Connect/disconnect pop up message in Skylight should be an user option
- SBM 16530 Device not found on Skylight after disconnect and remove device quickly

2.34.2 Component List

Component	Revision
Skylight.exe	13.0.1409.1
QmiPlugin.dll	12.0.1408.0
GobiApi.dll	4.2.1409.0

2.34.3 Known Issues

- Device drivers are not included and must be installed separately

2.35 Build 4193

2.35.1 Change Details

- SBM 16199 Skylight occasionally failed to detect EM7355 module installed.
- SBM 16290 [Skylight] "GPS monitor is not responding" after Enable sensors window pops up
- SBM 16272 [Skylight] Skylight GUI doesn't show 'No Service', instead shows 'Searching...' forever
- SBM 16274 [Skylight] The start tracking button in GPS monitor takes a long time to start working
- SBM 16285 [Skylight] Skylight screen is blank when switching images

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 28 of 31
-------------	--	-----------	------------	---------------

- SBM 16335 Skylight stuck in "Searching..." with MC7350
- SBM 16345 [Skylight] Number in skylight has no unit of measurement
- SBM 16387 [Skylight] The "Location and Other Sensors" window is not displayed after clicking on start tracking
- SBM 16397 [Skylight] "Skylight stopped working" pops up when uninstalling
- SBM 16421 [Skylight] After changing the GPS Measurement System Setting to Imperial the HEPE value is still in Metric

2.35.2 Component List

Component	Revision
Skylight.exe	13.0.1409.0
QmiPlugin.dll	12.0.1408.0
GobiApi.dll	4.2.1408.0

2.35.3 Known Issues

- Device drivers are not included and must be installed separately
- SBM 16402 Logging out and Logging in of PC will cause GPS Monitor to be unresponsive

2.36 Build 4173

2.36.1 Change Details

- 05123 [G5K][Skylight] Wrong timestamps displayed for received SMS messages
- 09961 [Watcher][TC102] Watcher stuck on "Searching...please wait" after rescanning for available networks
- 11218 HEPE values between GPSLOC and GPS Monitor do not match
- 12928 [Skylight] Add support for APN enable/disable flags
- 15546 [Skylight] Jumps to profiles when changing network selection to manual (Win 8.1 x64)
- 15806 [Skylight] Warning appears when disconnect button is pressed
- 15808 [Skylight] Manual Activation failed due to missing SID
- 15820 [Skylight] Occasional GPS monitor crashes
- 15823 Skylight unresponsive after successive opening and closing
- 15851 Modem gets stuck in LPM mode and Skylight shows "Device Safe Mode Temp" after Airplane mode is enabled in Skylight
- 15868 GPS monitor fails to detect modem after driver reinstallation (restart required)
- 16073 [Skylight] B4166 -- Skylight shows "Failed to turn radio off" after resume from S3/S4/Restart with Wireless switch off.
- 16091 [Skylight] Skylight crashes when coming back from sleep mode
- 16148 [Skylight] GPS Monitor shows no satellites even after a GPS fix is obtained
- 16150 [Skylight] Radio Access Technology field in Network Selection (advanced mode) is shown when it should be hidden
- 16207 After RTN reset, Skylight prompts warning message "Attempted an unsupported operation."

2.36.2 Component List

Component	Revision
Skylight.exe	13.0.1408.0
QmiPlugin.dll	12.0.1408.0

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 29 of 31
-------------	--	-----------	------------	---------------

GobiApi.dll	4.2.1406.0
-------------	------------

2.36.3 Known Issues

- Device drivers are not included and must be installed separately

2.37 Build 4166

2.37.1 Change Details

- 13769 Display correct state during firmware image switch
- 15187 Dynamically update HDR packet error rate in About.Advanced.Network screen
- 15531 Added eHRPD info in About.Advanced.Network screen
- 15216 Improved network name display time after manual network selection
- 15240 Enabled manual activation option for Sprint
- 15590 Fixed auto launch browser on data connect functionality
- 15445 Updated error message when modem in LPM due to modem configuration issues
- 15509 Fixed display of "Roaming charges may apply" message when not roaming
- 15529 Fixed GPS Monitor crash when changing display appearance percentage
- 15547 Fixed crash when modifying GPS options during modem reset
- 15763 Updated APN database for T-Mobile

2.37.2 Component List

Component	Revision
Skylight.exe	13.0.1407.0
QmiPlugin.dll	12.0.1407.1
GobiApi.dll	4.2.1406.0

2.37.3 Known Issues

- Device drivers are not included and must be installed separately

2.38 Build 4140

2.38.1 Change Details

- 15186 Location Fix GPS settings no longer revert back to default values
- 15511 Fixed issue which caused "DUT cannot receive GPS signal" error
- 15336 Added GPS Monitor synchronization with 64-bit Windows Radio Manager (must use 64-bit installer)
- 15533 Auto application launch no longer invoke 2 browser windows

2.38.2 Component List

Component	Revision
Skylight.exe	13.0.1406.0
QmiPlugin.dll	12.0.1406.0
GobiApi.dll	4.2.1406.0

2.38.3 Known Issues

- Device drivers are not included and must be installed separately

Document #:		Revision:	Build 4601	Page 30 of 31
-------------	--	-----------	------------	---------------

2.39 Build 4130

2.39.1 Change Details

- 07814 GPS Monitor uses Windows Location Sensor APIs to sync with Win8
- 14918 GPS monitor no longer stop working during driver reinstallation
- 15033 Stop tracking (Cancel button) is now working properly in GPS Monitor
- 15199 “Display GPS” button no longer missing

2.39.2 Component List

Component	Revision
Skylight.exe	13.0.1405.2
QmiPlugin.dll	12.0.1405.0
GobiApi.dll	4.2.1405.2

2.39.3 Known Issues

- Device drivers are not included and must be installed separately
- 15186 Location Fix GPS settings always revert back to the default values

2.40 Build 4106

2.40.1 Change Details

- 13866 Added advanced Sprint network info
- 11008 Added Sprint MIP error reporting
- 11854 Sprint RTN UI improvements
- 14606 Fixed occasional profile update error message during Sprint HFA
- 14441 Password field is now displayed for all profiles
- 14442 Correctly save host profile passwords
- 14630 Added SMS toast notifications
- 14750 Newly received SMS messages no longer marked as read
- 07814 GPS Monitor is now in sync with Windows location sensor setting
- 13479 MSI installer will only run on Windows 7 and newer operating systems

2.40.2 Component List

Component	Revision
Skylight.exe	13.0.1404.2
QmiPlugin.dll	12.0.1404.2
GobiApi.dll	4.2.1405.0

2.40.3 Known Issues

- Device drivers are not included and must be installed separately

2.41 Build 4094

2.41.1 Change Details

- 13981 Added OMA DM enterprise policy reject code support

SIERRA WIRELESS, INC.

Document #:		Revision:	Build 4601	Page 31 of 31
-------------	--	-----------	------------	---------------

- 14357 Fixed issue where manual network selection fails on some networks
- 13753 Fixed Win 8 connection state sync issue when running 5.x firmware
- 13601/13486/13311 Added support for 3GPP2 SMS with 7bit, 8bit, UCS2 SMS encoding
- 13669/13503 Added concatenated 3GPP2 SMS support
- 13575 Fixed issues related to UCS2 encoded MO SMS
- 14152 Filter + from MO SMS destination number
- 14034 Fixed multiple incoming SMS sound play when receiving concatenated SMS
- 13996 "User Options->Profile -> Auto-Create" is now defaulted to "Never"
- 13616 Fixed Japanese translation of "Enable Airplane mode on exit"
- 13999 Fixed Japanese translation of TCP/IP settings
- 13997 Removed "Network Selection" configuration page on Win8
- 13822/13646 Added support for long profile name
- 14070 Fixed byte counters issue on Win8 running 5.x firmware
- 14112 Added Dutch localization support

2.41.2 Component List

Component	Revision
Skylight.exe	13.0.1403.0
QmiPlugin.dll	12.0.1403.2
GobiApi.dll	4.1.1403.2

2.41.3 Known Issues

- Device drivers are not included and must be installed separately

2.42 Build 4072

2.42.1 Change Details

- 11104 Initial release

2.42.2 Component List

Component	Revision
Skylight.exe	12.0.1402.1
GobiApi.dll	4.1.1402.2
SwiCardDetectEx.dll	11.3.1402.1
*.msi	6.0.4072

2.42.3 Known Issues

- Device drivers are not included and must be installed separately
- Auto-launch on device detection not supported